QUICK INSTALLATION GUIDE
GUIDE D'INSTALLATION RAPIDE

DM5210

DYNAMIC LINE

ONE FOR ALL
ASSISTANT APP

Available on the **App Store**
Get it on **Google play**

Connect with us

facebook.com/ oneforallworldwide
@oneforall.worldwide
linkedin.com/ company/one-for-all-worldwide/
youtube.com/ user/oneforallproducts

20 kg

max 50"

VESA
Universal
300 x 200 max

START

1a CLAMP INSTALLATION
for 12–50mm thickness desks

1b GROMMET INSTALLATION
for 12–50mm thickness desks
& Ø10–60mm installation holes

M
D
F
P

P
N
D
G

2
B
O
C
I
A
H
O
O
O

3
P
E
L
K

4a VESA:
75x75 100x100
M-A M-B
M-C
Too Long Too Short
TOP

4b VESA:
200x200 200x250
250x200 200x300
300x200
M-A M-B
M-C
Q
Too Long Too Short
T S
R

Parts list:

A
B 2 x
C 2 x
D
E 2 x
F

G
H
I 2 x
J
K 2 x M8
L 2 x M8x35

M M8x55
N M8x130
O 4mm Allen key
P 6mm Allen key

Q 2x
R 4 x D5
S 4 x M5
T 8mm

Package M

M-A 8 x M4x12mm
M-C 8 x D5
M-B 8 x M5x12mm

5 2+

CAUTION: Do not release the monitor immediately after hanging and wait until you are sure it is stable in its position to prevent injury to personnel or equipment. If the arm rises or falls, refer to the next step for adjustment.

UNLOCK   LOCK

6 2+
P

To properly balance the arm with monitors mounted, adjust the spring tension using the supplied Allen Key as follows:

First, position and firmly hold the arm horizontally as shown. Ask for assistance should you require it.

CAUTION: To avoid damage to monitors or mount, always keep the arm in a horizontal position while making adjustments. Again, ask for assistance if required.

– + If the arm **drops,** turn the adjustment screw clockwise until it stays in a horizontal position.

– + If the arm **rises,** turn the adjustment screw counter-clockwise until it stays in a horizontal position.

CAUTION:
DO NOT over tighten the screws.

7
J

Note: If the display does not stop at your desired position, adjust the screws using the tools as shown.
P
P

CAUTION:
DO NOT rotate the monitor past rear edge of desk to avoid an unstable situation that may cause tipping.

FINISH